APARTMENT INTERIOR RENOVATION DETAILS IN AUSTIN

Interior renovations · Austin, Texas



Kitchen cabinetry, appliances and finish details, documented May 6, 2026.

DOCUMENTED SCOPE
Unit interiors, kitchen drywall repairs and leasing-office additions.

PHOTO RECORD
May 6, 2026: kitchen, living area and bathroom finishes.

RECORD STATUS
Documented project details. Completion unverified.

Progress records do not establish final acceptance, performance, a client endorsement or a before-and-after result.

Read the full project record and its dated photographs:
https://www.trockgc.com/projects/austin-apartment-interiors

MULTIFAMILY EXTERIOR RENOVATION IN BOYNTON BEACH

Exterior renovation · Boynton Beach, Florida



Previous exterior paint colors, photographed September 30, 2026. This image shows the old finish, not the completed repaint.

DOCUMENTED SCOPE
Door and balcony painting, with punch coordination recorded during the work.

PHOTO RECORD
September 14 and 30, 2026: balcony and exterior elevations; the main view shows the previous paint colors.

FIELD REPORT
October 7, 2026: painting progress, marked punch areas and weather-responsive work.

RECORD STATUS
Work in progress in the dated records. Completion unverified.

Progress records do not establish final acceptance, performance, a client endorsement or a before-and-after result.

Read the full project record and its dated photographs:
https://www.trockgc.com/projects/boynton-beach-exterior-renovation

EXTERIOR PAINTING & FACADE REPAIRS IN DALLAS

Exterior renovation · Dallas, Texas



Exterior painting stage documented October 5, 2026.

DOCUMENTED SCOPE
Exterior painting, facade mesh repairs, parking-garage awning removal and building-sign removal.

FIELD REPORT
October 6, 2026: exterior work and earlier rain-delay entries.

PHOTO RECORD
October 5 and 8, 2026: painting, facade mesh work and awning-removal details.

RECORD STATUS
Work in progress in the dated records. Completion unverified.

Progress records do not establish final acceptance, performance, a client endorsement or a before-and-after result.

Read the full project record and its dated photographs:
https://www.trockgc.com/projects/dallas-facade-renovation

MULTIFAMILY FIRE-LOSS RECONSTRUCTION IN DALLAS

Disaster restoration · Dallas, Texas



Exterior reconstruction and temporary barriers, documented October 8, 2026.

DOCUMENTED SCOPE
Insulation installation, fur-down framing and exterior enclosure work.

FIELD REPORT
September 21, 2026: construction progress and inspection-dependent next steps.

PHOTO RECORD
October 8, 2026: exterior framing, enclosure and temporary barriers.


RECORD STATUS
Work in progress in the dated records. Completion unverified.

Progress records do not establish final acceptance, performance, a client endorsement or a before-and-after result.

Read the full project record and its dated photographs:
https://www.trockgc.com/projects/dallas-fire-reconstruction

MULTIFAMILY LANDING RECONSTRUCTION IN URBANA

Exterior renovation · Urbana, Illinois



Stair and landing construction documented September 30, 2026.

DOCUMENTED SCOPE
Exterior landing reconstruction, with stair access and landing membrane details photographed.

PHOTO RECORD
September 30 and October 1, 2026: stair and landing construction, followed by a membrane detail.

RECORD STATUS
Documented project details. Completion unverified.

Progress records do not establish final acceptance, performance, a client endorsement or a before-and-after result.

Read the full project record and its dated photographs:
https://www.trockgc.com/projects/urbana-landing-reconstruction